

Work Order ID 152419

Monday, October 24, 2016 11:40:47 AM

152419

Page 1

Item ID: D4030-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Long Basket Assembly (350)
Start Date: 11/3/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 11/4/2016 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: DAS 21 9-89 Date: OCT 24 2016 Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D4030	D								
100	Pick Kit	0.00							
100									
Packaging	Memo	0.00							
Packaging									
110	Assemble as per dwg	0.00							
110									
HandFinish	Memo	0.16							
Hand Finishing									
120	QC5- Inspect part completeness to step on W/O	0.00							
120									
QC	Memo	0.00							
Quality Control									

DEC 20 2016 DAS 6 9-89

1x of all 16(12)cc

① 16-12-23 DAS 9 9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval 	
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause				FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong	☐
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions	☐
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance	☐
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect	☐
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved	☐
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing	☐
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish	☐
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread	☐
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence	☐
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____							
Misidentified	☐	Past Due	☐								

Work Order ID 152419

Monday, October 24, 2016 11:40:47 AM

152419

Page 2

Item ID: D4030-041 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Long Basket Assembly (350)
Start Date: 11/3/2016 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 11/4/2016 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130	Identify as per dwg & Stock Location: _____	0.00							
130									
Packaging	Memo	0.00							
Packaging									
140	QC21- Final Inspection - Work Order Release	0.00							
140									
QC	Memo	0.02							
Quality Control									

DAS 28 9-89
JAN 03 2017
DAS 21 9-89
JAN 06 2017
DAS 21 9-89
JAN 04 2017

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					

Picklist Print

Monday, October 24, 2016 11:40:47 AM

Page 1

Work Order ID: 152419

152419

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 11/3/2016

Required Date: 11/4/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:A new issue DD 10.03.23 verified by:EC IPP Rev:B as per dwg revB DD 10.04.20 verified by:EC IPP Rev:C as per dwg revC DD 10.08.18 verified by:EC IPP Rev D 12.03.27 per NCR12-1239 EC verified by:JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2530 *D2530* Handle Weldment		Manufactured	No			100	Each	7.0000	1	1		DEC 20 2016	DAS 6 9-89
Location ST379 145544 147255 Loc Qty 7 3 4 Loc Code													
D2535 *D2535* Spring		Manufactured	No			100	Each	56.0000	2	2		DEC 20 2016	DAS 6 9-89
Location ST008 144488 146275 148592 Loc Qty 56 6 25 25 Loc Code													
D2537 *D2537* Bushing		Manufactured	No			100	Each	58.0000	2	2		DEC 20 2016	DAS 6 9-89
Location ST008 141583 145899 148918 Loc Qty 58 1 32 25 Loc Code													
D3913-041 *D3913-041* Long Basket Base Assembly, 350		Manufactured	No			100	Each	0.0000	1	1			DAS 6 9-89

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Page 2

Monday, October 24, 2016 11:40:47 AM

Work Order ID: 152419

152419

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 11/3/2016

Required Date: 11/4/2016

Start Qty: 1.00

Required Qty: 1.00

D3914-041 Manufactured No

100 Each 0.0000 1 1

D3914-041

Long Basket Lid Assembly (350)

**

B151917 (16) 11/16/12/21

D3917-3 Manufactured No

100 Each 94.0000 6 6

D3917-3

Washer

**

DEC 20 2016

BA: 6 9-8

Location

Loc Qty

Loc Code

ST058

94

146855

8

147428

25

148671

24

151081

37

D3953-3 Manufactured No

100 Each 42.0000 2 2

D3953-3

Gas Spring Stud, Lid

**

DEC 20 2016

DAS 6 9-89

Location

Loc Qty

Loc Code

ST062

20

149582

20

ST064A

22

147675

10

148400

12

D3953-7 Manufactured No

100 Each 32.0000 2 2

D3953-7

Spring Spacer

**

DEC 20 2016

DAS 6 9-89

Location

Loc Qty

Loc Code

ST062

4

144665

4

ST064A

28

147641

16

148382

12

Monday, October 24, 2016 11:40:47 AM

Shop Packet Print

Page 2

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval	
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐			
Design ☐	☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐			
Doc/Data ☐	☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐			
Equip/Tooling ☐	☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐			
Handling/Pre ☐	☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐			
Material ☐	☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐			
Internal Transport ☐	☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐			
Tribal Knowledge ☐	☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐			
LOA ☐	☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐			
Substation ☐	☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐			
Past Expiry Date ☐	☐	Manufacturing Process ☐	OTHER :						
Misidentified ☐	☐	Past Due ☐							

Picklist Print

Monday, October 24, 2016 11:40:47 AM

Page 3

Work Order ID: 152419

152419

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 11/3/2016

Required Date: 11/4/2016

Start Qty: 1.00

Required Qty: 1.00

D3953-9 Manufactured No 100 Each 63.0000 2 2

D3953-9

Gas Spring Washer

DEC 20 2016

DAS
6
9-89

Location Loc Qty Loc Code

ST062 8

147022 8

ST064A 55

145912 55

D3953-17 Manufactured No 100 Each 38.0000 2 2

D3953-17

Gas Spring Spacer

DEC 20 2016

DAS
6
9-89

Location Loc Qty Loc Code

ST062 38

145690 9

147373 13

149542 16

D3953-19 Manufactured No 100 Each 30.0000 1 1

D3953-19

Gas Spring Bracket

DEC 20 2016

DAS
6
9-89

Location Loc Qty Loc Code

ST062 16

138913 2

145653 14

ST064A 14

147350 14

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐				

Picklist Print

Page 4

Monday, October 24, 2016 11:40:47 AM

Work Order ID: 152419

152419

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 11/3/2016

Required Date: 11/4/2016

Start Qty: 1.00

Required Qty: 1.00

D3953-21 Manufactured No

100 Each 26.0000 1 1

D3953-21

Gas Spring Bracket

**

DEC 10 2016

DAS
6
9-89

Location Loc Qty Loc Code

ST063 26

145806 12

147443 14

D3969-3 Manufactured No

100 Each 14.0000 1 1

D3969-3

Spring (Basket Lid)

**

DEC 10 2016

DAS
6
9-89

Location Loc Qty Loc Code

ST365 14

144499 4

148841 10

AN3-14A Purchased No

100 Each 81.0000 4 4

AN3-14A

Bolt

**

DEC 10 2016

DAS
6
9-89

Location Loc Qty Loc Code

over003 78

m135056 48

m135600 30

ST349 3

m134852 3

AN3-16A Purchased No

100 Each 55.0000 2 2

AN3-16A

Bolt

**

DEC 10 2016

DAS
6
9-89

Location Loc Qty Loc Code

GA 45

117441 45

ST348 10

M134943 10

Monday, October 24, 2016 11:40:47 AM

Shop Packet Print

Page 4

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐
Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐				

Picklist Print

Monday, October 24, 2016 11:40:47 AM

Page 5

Work Order ID: 152419

152419

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 11/3/2016

Required Date: 11/4/2016

Start Qty: 1.00

Required Qty: 1.00

AN5-17A

Purchased

No

100

Each

121.0000

4

4

AN5-17A

Bolt

DAS
6
9-89

DEC 20 2016

Location

Loc Qty

Loc Code

GA

29

117872

29

over003

75

m135297

75

ST337

17

m134606

3

m134762

14

4

AN4-12

Purchased

No

100

Each

64.0000

3

3

AN4-12

Bolt

DAS
6
9-89

DEC 20 2016

Location

Loc Qty

Loc Code

ST344

64

m134370

1

m134738

13

m135046

25

m135408

25

3

AN310-4

Purchased

No

100

Each

118.0000

3

3

AN310-4

Nut

DAS
6
9-89

DEC 20 2016

Location

Loc Qty

Loc Code

GA

25

M127815

25

OVER007

50

M135704

50

ST331

43

M134955

1

M135442

42

3

Monday, October 24, 2016 11:40:47 AM

Shop Packet Print

Page 5

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td style="border: none;">Skid-tube ☐</td> <td style="border: none;">Cross tube ☐</td> <td style="border: none;">Water Jet ☐</td> <td style="border: none;">Engineering ☐</td> </tr> <tr> <td style="border: none;">Machining ☐</td> <td style="border: none;">Small Fab ☐</td> <td style="border: none;">Prod. Eng. Coord. ☐</td> <td style="border: none;">Quality ☐</td> </tr> <tr> <td style="border: none;">Thermoforming ☐</td> <td style="border: none;">Finishing ☐</td> <td style="border: none;">Rec/Store/Packaging ☐</td> <td style="border: none;">Other ☐</td> </tr> <tr> <td style="border: none;">Large Fab ☐</td> <td style="border: none;">Composite ☐</td> <td style="border: none;">Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition																					
								Completed By																	
								Lead hand / Supervisor Approval Verification																	
								QC / QA Coordinator Approval																	
Root Cause		FAULT CATEGORY																							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐	OTHER : _____																			

Picklist Print

Monday, October 24, 2016 11:40:47 AM

Page 6

Work Order ID: 152419

152419

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 11/3/2016

Required Date: 11/4/2016

Start Qty: 1.00

Required Qty: 1.00

AN310C4
Nut
AN310C4

Purchased

No

100

Each

103.0000

2

2

DAS
6
9-89

DEC 20 2016

Location

Loc Qty

Loc Code

OVER007

64

M135297

29

M135895

35

ST331

39

M134762

39

2

MS21042L3
Nut
MS21042L3

Purchased

No

100

Each

1,463.000

6

6

DAS
6
9-89
DEC 20 2016

Location

Loc Qty

Loc Code

FP001

7

M130922

7

GA

225

m134360

108

m135135

117

OVER007

600

m135767

600

ST303

631

m135530

600

m135600

31

135945

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Monday, October 24, 2016 11:40:47 AM

Page 7

Work Order ID: 152419

152419

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 11/3/2016

Required Date: 11/4/2016

Start Qty: 1.00

Required Qty: 1.00

MS21042L5

Purchased

No

100

Each

354.0000

4

4

MS21042L5

Nut

**

DAS
6
9-89

DEC 20 2016

Location

Loc Qty

Loc Code

GA

53

m127813

53

ST303

301

m135297

131

m135544

100

m135774

70

MS24665-151

Purchased

No

100

Each

140.0000

3

3

MS24665-151

Cotter Pin

**

DAS
6
9-89

DEC 20 2016

Location

Loc Qty

Loc Code

GA

60

m128401

60

ST289

80

m135274

80

MS24665-300

Purchased

No

100

Each

121.0000

2

2

MS24665-300

COTTER PIN

**

DAS
6
9-89

DEC 20 2016

Location

Loc Qty

Loc Code

GA

28

118234

28

ST288

93

m135046

93

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
Root Cause		FAULT CATEGORY							
Environment ☐	☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐			
Design ☐	☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐			
Doc/Data ☐	☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐			
Equip/Tooling ☐	☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐			
Handling/Pre ☐	☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐			
Material ☐	☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐			
Internal Transport ☐	☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐			
Tribal Knowledge ☐	☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐			
LOA ☐	☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐			
Substation ☐	☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐			
Past Expiry Date ☐	☐	Manufacturing Process ☐	OTHER : _____						
Misidentified ☐	☐	Past Due ☐							

Picklist Print

Monday, October 24, 2016 11:40:47 AM

Page 8

Work Order ID: 152419

152419

Parent Item: D4030-041

D4030-041

Parent Item Name: Long Basket Assembly (350)

Start Date: 11/3/2016

Required Date: 11/4/2016

Start Qty: 1.00

Required Qty: 1.00

NAS1149F0432P

Purchased

No

100

Each

1,449.000

6

6

NAS1149F0432P

WASHER

DEC 20 2016

DAS 6 9-89

Location

Loc Qty

Loc Code

ST260a

1000

M135704

1000

ST262

449

M134955

449

NAS1149F0563P

Purchased

No

100

Each

168.0000

4

4

NAS1149F0563P

Washer

DEC 20 2016

DAS 6 9-89

Location

Loc Qty

Loc Code

ST262

168

m134852

168

NAS1149F0332P

Purchased

No

100

Each

1,350.000

8

8

NAS1149F0332P

Washer

DEC 20 2016

DAS 6 9-89

Location

Loc Qty

Loc Code

GA

282

m133709

282

ST262

1068

m135544

1068

NAS1149C0432R

Purchased

No

100

Each

1,185.000

2

2

NAS1149C0432R

WASHER

DEC 20 2016

DAS 6 9-89

Location

Loc Qty

Loc Code

GA

800

m125807

427

m134676

373

ST266

385

m135544

385

Monday, October 24, 2016 11:40:47 AM

Shop Packet Print

Page 8

DQA: _____ Date: _____


WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
				Completed By _____					
				Lead hand / Supervisor Approval Verification					
				QC / QA Coordinator Approval					
Root Cause		FAULT CATEGORY							
Environment ☐	☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐			
Design ☐	☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐			
Doc/Data ☐	☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐			
Equip/Tooling ☐	☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐			
Handling/Pre ☐	☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐			
Material ☐	☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐			
Internal Transport ☐	☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐			
Tribal Knowledge ☐	☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐			
LOA ☐	☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐			
Substation ☐	☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐			
Past Expiry Date ☐	☐	Manufacturing Process ☐	OTHER : _____						
Misidentified ☐	☐	Past Due ☐							

ITEM	QTY -041	P/N	DESCRIPTION
	X	D4030-041	LONG BASKET ASSY (350)
1	1	D2530	HANDLE WELDMENT
2	2	D2535	SPRING
3	2	D2537	BUSHING
4	1	D3913-041	LONG BASKET BASE ASSY (350)
5	1	D3914-041	LONG BASKET LID ASSY (350)
6	6	D3917-3	WASHER
7	2	D3953-3	GAS SPRING STUD, LID
8	2	D3953-7	GAS SPRING SPACER
9	2	D3953-9	GAS SPRING WASHER
10	2	D3953-17	GAS SPRING SPACER
11	1	D3953-19	GAS SPRING BRACKET
12	1	D3953-21	GAS SPRING BRACKET
13	1	D3969-3	SPRING
14	4	AN3-14A	BOLT, MACHINE
15	2	AN3-16A	BOLT, MACHINE
16	3	AN4-12	BOLT, MACHINE
17	4	AN5-17A	BOLT, MACHINE
18	2	AN310C4	NUT, PLAIN, CASTELLATED
19	3	AN310-4	NUT, PLAIN, CASTELLATED
20	6	MS21042L3	NUT, SELF-LOCKING
21	4	MS21042L5	NUT, SELF-LOCKING
22	2	MS24665-300	COTTER PIN
23	3	MS24665-151	COTTER PIN
24	2	NAS1149C0432R	WASHER
25	6	NAS1149F0432P	WASHER
26	8	NAS1149F0332P	WASHER
27	4	NAS1149F0563P	WASHER



D4030-041 LONG BASKET ASSY (350)
(MESH SHOWN LOCALLY FOR CLARITY)

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 152419 MJS


16-10-24

RELEASED
2013-08-16

NOTES:
1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: N/A
7) WEIGHT: 72 lbs APPROX

D	REFORMAT FOR CLARITY. PICTORIAL UPDATE TO MULTIPLE VIEWS DUE TO CHANGES IN SUB ASSEMBLIES.	AJS	13.07.18
C	QTY FOR ITEMS #30 & #31 UNDER -043 WERE MISSING (B8-1); QTY FOR ITEM #3 WAS 4 (D6-1); ONLY 2 ARE REQUIRED, AFFECTS SECTION C-C (D3-3).	MB	10.07.23
B	AN5-21A BOLT WAS AN5-19A: BOM & (D3-3)	JPH	10.04.06
A	NEW ISSUE	JPH	10.03.16
REV.	DESCRIPTION	BY	DATE
DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED		DRAWING NO.	REV. D
MFG. APPR.		D4030	SHEET 1 OF 4
APPROVED		TITLE	SCALE
DE APPR.		LONG BASKET ASSY (350)	NTS
DATE	13.07.18	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	

ITEM	QTY	P/N	DESCRIPTION
	X	D4030-043	LONG BASKET ASSY, LIGHT LID (350)
1	1	D2530	HANDLE WELDMENT
2	2	D2535	SPRING
3	2	D2537	BUSHING
4	1	D3913-041	LONG BASKET BASE ASSY (350)
5	1	D3915-041	LIGHT LID ASSY, LONG BASKET
6	6	D3917-3	WASHER
7	2	D3953-3	GAS SPRING STUD, LID
8	2	D3953-7	GAS SPRING SPACER
9	2	D3953-9	GAS SPRING WASHER
10	2	D3953-17	GAS SPRING SPACER
11	1	D3953-19	GAS SPRING BRACKET
12	1	D3953-21	GAS SPRING BRACKET
13	1	D3969-3	SPRING
14	4	AN3-14A	BOLT
15	2	AN3-20A	BOLT
16	3	AN4-12	BOLT
17	2	AN5-17A	BOLT
18	2	AN5-21A	BOLT
19	3	AN310-4	NUT, PLAIN, CASTELLATED
20	2	AN310C4	NUT, PLAIN, CASTELLATED
21	6	MS21042L3	NUT, SELF-LOCKING
22	4	MS21042L5	NUT, SELF-LOCKING
23	3	MS24665-151	COTTER PIN
24	2	MS24665-300	COTTER PIN
25	6	NAS1149F0432P	WASHER
26	4	NAS1149F0563P	WASHER
27	8	NAS1149F0332P	WASHER
28	2	NAS1149C0432R	WASHER






D4030-043 LONG BASKET ASSY, LIGHT LID (350)
(MESH SHOWN LOCALLY FOR CLARITY)

RELEASED
2013-08-16

NOTES:
1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: N/A
7) WEIGHT: 57 lbs APPROX

DESIGN	AJS	DART AEROSPACE LTD	
DRAWN	AJS	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. D
MFG. APPR.		D4030	SHEET 2 OF 4
APPROVED		TITLE	SCALE
DE APPR.		LONG BASKET ASSY (350)	NTS
DATE	13.07.18	COPYRIGHT © 2010 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PROPRIETARY AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			

8 7 6 5 4 3 2 1




D4030-041 LONG BASKET ASSY (350) (SHOWN)
(MESH SHOWN LOCALLY OR REMOVED FOR CLARITY)

D4030-043 SHORT BASKET ASSY, LIGHT LID (350) (SIMILAR)
(MESH SHOWN LOCALLY OR REMOVED FOR CLARITY)


DESIGN	AJS	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	AJS		
CHECKED	<i>[Signature]</i>	DRAWING NO. D4030	REV. D SHEET 3 OF 4
MFG. APPR.	<i>[Signature]</i>	TITLE LONG BASKET ASSY (350)	SCALE NTS
APPROVED	<i>[Signature]</i>	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	
DE APPR.	<i>[Signature]</i>		
DATE	13.07.18		

8 7 6 5 4 3 2 1

AN4-12 BOLT, MACHINE
D3917-3 WASHER, 2X
NAS1149F0432P WASHER, 2X
AN310-4 NUT, CASTELLATED
MS24665-151 COTTER PIN




DETAIL A D8-3
D5-3



DETAIL B D3-3

AN4-12 BOLT, MACHINE
D3917-3 WASHER, 2X
NAS1149F0432P WASHER, 2X
AN310-4 NUT, CASTELLATED
MS24665-151 COTTER PIN

D4030-041: AN3-16A BOLT, MACHINE
MS21042L3 NUT
D4030-043: AN3-20A BOLT, MACHINE
MS21042L3 NUT




SECTION C-C B4-3
B6-3

D4030-041: AN5-17A BOLT, MACHINE
D2537 BUSHING
D2535 SPRING
NAS1149F0563P WASHER
MS21042L5 NUT
D4030-043: AN5-21A BOLT, MACHINE
D2537 BUSHING
D2535 SPRING
NAS1149F0563P WASHER
MS21042L5 NUT

AN5-17A BOLT, MACHINE
NAS1149F0563P WASHER
MS21042L5 NUT

D2530
HANDLE WELDMENT
REF




VIEW F-F C3-4

D3953-17 GAS SPRING SPACER
D3953-21 GAS SPRING BRACKET
AN3-14A BOLT, MACHINE
NAS1149F0332P WASHER, 2X
MS21042L3 NUT
2 PL

D3953-3 GAS SPRING STUD, LID
D3953-7 GAS SPRING SPACER
D3953-9 GAS SPRING SPACER
NAS1149C0432R WASHER
AN310C4 NUT, CASTELLATED
MS24665-300 COTTER PIN

D3969-3 SPRING
REF

SECTION D-D B2-3



SECTION E-E B1-3

D3953-17 GAS SPRING SPACER
D3953-19 GAS SPRING BRACKET
AN3-14A BOLT, MACHINE
NAS1149F0332P WASHER, 2X
MS21042L3 NUT
2 PL
D3953-3 GAS SPRING STUD, LID
D3953-7 GAS SPRING SPACER
D3953-9 GAS SPRING SPACER
NAS1149C0432R WASHER
AN310C4 NUT, CASTELLATED
MS24665-300 COTTER PIN

D3969-3 SPRING
REF

RELEASED
2013-08-16
M

DESIGN	AJS	DART AEROSPACE LTD	
DRAWN	AJS	HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. D
MFG. APPR.		D4030	SHEET 4 OF 4
APPROVED		TITLE	SCALE
DE APPR.		LONG BASKET ASSY (350)	NTS
DATE	13.07.18	COPYRIGHT © 2010 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL, AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR REPRODUCED TO ANY OTHER PERSON OR ENTITY WITHOUT THE WRITTEN PERMISSION FROM DART AEROSPACE LTD.			